DOCKETED	
Docket Number:	18-IEPR-06
Project Title:	Integrating Renewable Energy
TN #:	223859
Document Title:	Inverters Behaving Badly
Description:	Presentation by Lou Fonte at the June 20, 2018 IEPR Workshop on
	Renewable Integration and Electric System Flexibility
Filer:	Stephanie Bailey
Organization:	California ISO
Submitter Role:	Public
Submission Date:	6/19/2018 1:16:48 PM
Docketed Date:	6/19/2018



### **Inverters Behaving Badly**

Lou Fonte Senior Advisor, Grid Assets

California Energy Commission IEPR Workshop June 20, 2018

# Issue - Solar PV generation lost during the routine clearing of high voltage transmission line faults

- August 2016 April 2018: Experienced 13 transmission system faults that resulted in the unanticipated loss of inverter based generation.
  - All transmission line faults cleared in four cycles or less (normal high speed tripping)
  - Inverters should <u>not</u> have tripped nor ceased to operate for any of these events
  - In January 2017 CAISO and SCE brought this to WECC and NERC. NERC formed the Inverter based Resource Task Force (IRPTF) to investigate



### Summary of Transmission System Events

Date	Transmission Line	Solar PV Lost
8/16/2016 1145	Lugo – Mira Loma No.3 (500 kV)	1178 MW
8/16/2016 1404	Lugo – Mira Loma No.3 (500 kV)	234 MW
8/16/2016 1513	Lugo – Mira Loma No.2 (500 kV)	311 MW
8/16/2016 1519	Lugo – Mira Loma No.2 (500 kV)	30 MW
9/06/2016 1317	Kingbird – Whirlwind (220 kV)	755 MW
9/12/2016 1740	Antelope – Whirlwind (500 kV)	62 MW
11/12/2016 1000	Victorville Sub (LADWP) (220 kV)	231 MW
2/06/2017 1213	Antelope - Vincent No.2 (500 kV)	740 MW
5/10/2017	Hasayampa – Hoodoo Wash (500 kV)	543 MW
6/15/2017 1300	Victorville – McCullough (500 kV)	813 MW
10/09/2017 1212	Serrano – Chino (220 kV)	682 MW
10/09/2017 1214	Serrano – Valley (500 kV)	937 MW
4/20/2018 1711	Mira Loma – Vincent (500 kV)	694 MW

California ISO

Slide 3

### NERC IRPTF – Issue Identification

### Problem 1: system frequency calculation - resolved

- The NERC IRPTF studied the August 2016 events (Blue Cut Fire) and issued a report (6/2017) and its first Alert (6/20/2017)
- The task force identified that most of the inverters tripped due to erroneous calculation of system frequency. Report also identifies momentary cessation as an item for study.
- CAISO worked with inverter manufacturers to develop new frequency control settings and impacted inverters were updated

### Problem 2: momentary cessation - ongoing

 NERC IRPTF issued second report 2/2018 for Canyon 2 fire, which occurred in southern California on 10/02/2017. Momentary cessation and transient over voltage identified as main issues. Second NERC Alert issued 5/01/2018.



# CAISO and the NERC task force continue to investigate and identified other issues

### Problem 3: voltage issues - ongoing

- Solar PV can still be lost due to:
  - Inverters momentarily ceasing operation during transient voltages (low and high) – Momentary Cessation
  - Transient high voltage levels (typically >120%) NERC task force identified that manufacturers may not be using filters to accurately measure voltage – High Voltage or DC overcurrent trip
  - Both of the above items are addressed in NERC's second Alert
- NERC IRPTF issued draft Guidelines for inverter based generation for public comment, comments due June 29, 2018



#### Lack of National Standards

- There are no national standards that govern the performance and response for inverters connected to the high voltage transmission system
- There are national standards for inverters connected to the <u>distribution</u> system
  - IEEE 1547 and UL 1741
  - California has Rule 21 in place
- Generator owners typically specify inverters to be in compliance with distribution standards.
- These distribution standards are not compatible for interconnections to the high voltage electric system



#### Additional CAISO Actions

- Updating Generator Interconnection Agreements to include as <u>requirements</u> the recommendations in the second NERC Alert.
- Developing a solar PV database to include data on installed inverters and associated control settings
- Continuing to adjust contingency reserves
- Working with inverter manufacturers and generator owners to get accurate inverter models and conduct system studies to assess risk
- In May 2018, the CAISO filed a Standard Authorization Request (SAR) at NERC requesting the development of a new standard for inverter based generation




### **Appendix**

- NERC Blue Cut Fire Report
- https://www.nerc.com/pa/rrm/ea/1200\_MW\_Fault\_Induced
  Solar\_Photovoltaic\_Resource\_/1200\_MW\_Fault\_Induced
  Solar\_Photovoltaic\_Resource\_Interruption\_Final.pdf
- NERC Canyon 2 Report
- https://www.nerc.com/pa/rrm/ea/October%209%202017% 20Canyon%202%20Fire%20Disturbance%20Report/900% 20MW%20Solar%20Photovoltaic%20Resource%20Interru ption%20Disturbance%20Report.pdf



### Momentary Cessation Example



**V**<sub>mc</sub>: voltage threshold where momentary cessation occurs

**Δt**<sub>sr</sub>: delay of current injection after voltage recovers

 $\Delta t_{rr}$ : ramp duration of recovery in current injection

Inverters often return within <u>tens of</u> <u>seconds</u> when voltage conditions stabilize.

NERC Alert recommends that delay time be no longer than <u>0.1 sec</u>, and the total time to return upon voltage stabilization no longer than one sec



ISO Public