DOCKETED	
Docket Number:	01-AFC-07C
Project Title:	01-AFC-7C Russell City Energy Company
TN #:	246111
Document Title:	Bay Valve Service's Photos of Butterfly Valve Inspection and Disassembly
Description:	N/A
Filer:	Patricia Carlos
Organization:	California Energy Commission
Submitter Role:	Commission Staff
Submission Date:	9/15/2022 11:10:10 AM
Docketed Date:	9/15/2022


































































































DISASSEMBLY































































GEARBOX SPEC AND FAILURE ANALYSIS

Gearbox Ratio 1632 to 1	
Gearbox ratio at 90 degrees 408 to 1	
Gear reduction ratios	
Input gear 13 teeth	First gear ratio 3.92 to 1
Middle gear 51 teeth	
Middle gear reduction 9 teeth	Second gear ratio 5.33 to 1
Input gear to worm gear shaft 48 teeth	
Total gear reduction before worm gear shaft 20.91 to 1	
19.5 total turns of worm gear shaft for full 90 degrees of operation	
Average thickness of conical roller bearing .437"	
Lash on worm gear shaft allowed if conical roller bearing is destroyed 9.14 turn in open direction and 9.14 turn to closed direction	
Total turns of lash 18.28 turns which would equate to 4 to 5% of total stroke	
Diameter of quad gear 20.875"	
Avg diameter of disc seating surface 20.375"	
With the diameters between the disc and quad gear being so close to each other. it would almost be a direct correlation of the distance	

Between the disc and seat face and the distance of lash on worm gear due to bearing failure.