

DOCKETED

Docket Number:	17-BSTD-02
Project Title:	2019 Title 24, Part 6, Building Energy Efficiency Standards Rulemaking
TN #:	222992
Document Title:	Vince Cord Comments Water availability to wash condenser coils
Description:	N/A
Filer:	System
Organization:	Vince Cord
Submitter Role:	Public
Submission Date:	3/17/2018 3:52:48 PM
Docketed Date:	3/19/2018

Comment Received From: Vince Cord

Submitted On: 3/17/2018

Docket Number: 17-BSTD-02

Water availability to wash condenser coils

There should be a hose bib on any roof that has a condenser on it. It should be no more than 25 feet away from the condenser. Regular cleaning the coils is necessary to maintain efficiency.