

DOCKET	
07-AAER-3	
DATE	JUN 21 2008
RECD.	JUL 01 2008

HILLCREST POOL SERVICE
P.O. BOX 393
BROWNS VALLEY, CA. 95918
CL578310
(530)639-2338

June 21, 2008

California Energy Commission,
As a IPSSA member I do not agree with the position of the IPSSA Board of Regional Directors regarding the current language of Title 20. I feel the language as written should stand with the addition of language to include replacement motors. As a swimming pool repair and service contractor with close to 40 years of industry time it is time to get rid of those 20 to 30 year old energy hog pumps and make these pools correct. I have been doing this very thing for 15 to 20 years by down sizing 1.5hp to 2hp to .5hp or 3/4hp modern pumps with no lose in flow and some cases a slight increase, but with a great increase in energy efficiency.

Thank you

Johnny Palacio