

| DOCKETED | |
|-------------------------|--|
| Docket Number: | 25-OPT-02 |
| Project Title: | Prairie Song Reliability Project |
| TN #: | 270647 |
| Document Title: | Ruthie Brock Comments - ANOTHER BRUSH FIRE IN ACTON JUNE 13 2026 Part 1 |
| Description: | N/A |
| Filer: | System |
| Organization: | Ruthie Brock |
| Submitter Role: | Public |
| Submission Date: | 6/16/2026 11:38:38 AM |
| Docketed Date: | 6/16/2026 |

*Comment Received From: Ruthie Brock
Submitted On: 6/16/2026
Docket Number: 25-OPT-02*

ANOTHER BRUSH FIRE IN ACTON JUNE 13 2026 Part 1


Another brush fire driven by winds in Acton on June 13, 2026. This fire, now known as the Lemon Fire, is in east Acton and started approximately 1 mile northeast of the Prairie Song proposed site location.

Additional submitted attachment is included below.

Another wildfire in Acton 6/13/26



The screenshot above is from the Watch Duty App, and was taken at 4pm on June 13, 2026. The Lemon Fire started at approximately 2pm and was being pushed by moderate winds between 16 mph and 20mph blowing east. Residents in the upper elevations just north of the Lemon Fire's path on Steven Amber Way, reported gusts up to 35 mph.



Please note in the screenshot above that the winds in the east Acton corridor are elevated as compared to areas to the south and to the west. We have often said the wind "funnels" and accelerates through this area, just as it is now.

The Prairie Song Reliability Project is too risky to be sited in this east Acton corridor which is justifiably a designated VERY HIGH FIRE HAZARD SEVERITY ZONE. Its worth noting that the winds were blowing from the west to the east during this fire. This is not the usual wind pattern experienced in this east Acton area. The normal direction is for the winds to blow from north to south/southwest. Had this been the wind direction during this June 13th fire, the Prairie Song BESS would have been directly in its path. This fire started directly adjacent to where the 400 MW Humidor would have been built, had SORT and Acton not been successful stopping it in court.

So even if a fire does not originate at the PSRP BESS facility, it would be disastrous if a wildfire burned through this area and ignited any of it's 2,035 Lithium Iron Phosphate battery container units. It would be extremely difficult to evacuate residents and their animals, with many having limited egress which could be even more limited or totally eliminated during a potential toxic gas release. Also, it must be noted that the Elkhorn BESS facility sustained damage from smoke and particulate associated with the Vistra BESS Fire in Moss Landing, so even a fire that encroaches upon the PSRP could cause significant damage to the facility, even if not by the containers themselves burning. An event at PSRP could easily match or exceed the Vistra BESS fire which we know has harmed hundreds of residents and done untold environmental damage. And those residents had a unobstructed path to get away from the fire incident. Our residents would not.

****Please also note this is the SECOND brush fire in TWO months in Acton. The Crown Fire started on April 3rd spreading quickly by 24 to 36 mph winds blowing to the south/southwest, threatening many lives and homes.***

****As of 9am June 14th the Lemon Fire was at 47% containment and held to 300 acres.***

***Please do not approve the Prairie Song Reliability Project in Acton.
Ruthie Brock, Acton***