DOCKETED	
Docket Number:	15-MISC-02
Project Title:	2013 Building Energy Efficiency Standards
TN #:	204983
Document Title:	Dave Hegarty Comments: Bypass duct button (radio) on Software
Description:	N/A
Filer:	System
Organization:	Dave Hegarty
Submitter Role:	Public
Submission Date:	6/11/2015 7:04:29 PM
Docketed Date:	6/11/2015

Comment Received From: Dave Hegarty

Submitted On: 6/11/2015 Docket Number: 15-MISC-02

Bypass duct button (radio) on Software

Dear Staff: I have reported to the hotline and reported it to staff the issue of bypass button not working. I am trying find out why the bypass button is not working, (or if it is supposed to), but first i'd like to understand is it supposed to do something when pushed? Meaning is there or is there not a penalty for using a bypass duct? If there is supposed to be a penalty, then it does not show a difference in compliance with or without a bypass duct claim on the software. Understand? Trying to get an understanding from Staff as to â€æpenalty or no penalty†when the button is activated and if it is no penalty what is the button for? (could it be to indicate that it has a bypass duct and therefore needs a HERS verification to show on the CF1R)? And if that's the case, does staff then consider the HERS verification of the bypass, THE Penalty? From there, if determined this is the case, is it necessary to have 100% verification of bypass when applied in the â€æproduction†homes or can we sample? Respectfully dave