

California Quality LED Lamp Specification: Docket number 12-BSTD-03

Comments

1. Color Rendering: R9 of 0 is too low. Minimum value should be 15+. DOE testing of Caliper lamps shows most above 15. You may also want to explore a 90 CQS and the associated R9.
2. Color Appearance & Consistency should be within a 2-step in accordance with LRC guidelines for directional lamps (accent lamps).
3. Color Maintenance: Should be less than the Energy Star requirement for directional (accent) lamps. 2-step in accordance with LRC initial guidelines should be the requirement at 6,000hrs for a lamp that is designed for 35,000= hrs.

Sincerely;

Thor Scordelis
Manager, Global Product Marketing
Xicato, Inc.
4880 Stevens Creek Blvd.
San Jose, CA 95129