


DOCKETED

Docket Number:	21-AFC-02
Project Title:	Willow Rock Energy Storage Center
TN #:	265151
Document Title:	Willow Rock CURE Data Request 2 Response, Attachment DR143-1_Part2
Description:	Resubmission of files previously submitted through Kiteworks.
Filer:	Samantha G. Neumyer
Organization:	Climate Edge Law Group
Submitter Role:	Applicant Representative
Submission Date:	7/30/2025 2:43:50 PM
Docketed Date:	7/30/2025

Project #

GPH


Project #

Project #

The image consists of two photographs of wooden crates containing fossilized plant specimens. The top photograph shows a crate with the following labels: 'Top 1116', 'Box 74', 'Bottom 1131', and a central label with 'ZEV-CH-06-24', '8/10/24', 'Rosa mondia', 'Top: 1116', 'Bottom: 1131', and 'Box: 74'. The bottom photograph shows a similar crate with labels: 'Top 1131', 'Box 75', 'Bottom 1146', and a central label with 'ZEV-CH-06-24', '8/10/24', 'Rosa mondia', 'Top: 1131', 'Bottom: 1146', and 'Box: 75'. Both crates are filled with rows of small, grey, fossilized plant specimens. A yellow measuring tape is visible along the top edge of each crate.

Elevation	
Location	Rosamond,ca
Owner	CEC
Date	10/2/2024

Project #


[illegible]

TEST HOLE	zev-ch-06-24
DRILL DEPTH	2280.1
STATIC WATER TABLE	70
TESTED BY	CAM
COMMENTS	test 84- lugeon test -
COMMENTS	


Project #[illegible]

Elevation	
Location	Rosamond,ca
Owner	CEC
Date	10/2/2024

Project #

[illegible]


TEST HOLE	zev-ch-06-24	Elevation	
DRILL DEPTH	2280.1	Location	Rosamond,ca
STATIC WATER TABLE	70	Owner	CEC
TESTED BY	CAM	Date	10/2/2024
COMMENTS	test 88 - 48 secs - 8 oz/ losing water pressure very fast		
COMMENTS			

[illegible]

Project #


TEST HOLE	zev-ch-06-24
DRILL DEPTH	2080.1
STATIC WATER TABLE	70
TESTED BY	CAM
COMMENTS	test 96 - holding
COMMENTS	

Project #

[illegible]

TEST HOLE	zev-ch-06-24
DRILL DEPTH	2080.1
STATIC WATER TABLE	70
TESTED BY	CAM
COMMENTS	Test 104 - 4oz - 5:24
COMMENTS	

Project #

[illegible]

TEST HOLE	zev-ch-06-24
DRILL DEPTH	2080.1
STATIC WATER TABLE	70
TESTED BY	CAM
COMMENTS	Test 105 - Falling head 7:35 1 cup
COMMENTS	

Project #






[illegible]

Test 36 Holding

Elevation
Location
Owner
Date

Project #





GPH



Test 110 - Holding

Elevation
Location
Owner
Date

Project #

GPH

TEST HOLE	Test 111 Lugeon 4oz - 5:42
DRILL DEPTH	
STATIC WATER TABLE	
TESTED BY	
COMMENTS	
COMMENTS	

[illegible]

Test 112 - 4oz = 6:22

Project #

GPH

Project #

39 Top 621
Bot 606 Box 41

ZEV-CH-06-24
8/10/24
Rosamond, CA

Top: 621
Bottom: 636 Box: 41

ZEV-CH-06-24
8/10/24
Rosamond, CA

Box 41
Bottom 636 Box 43