

## DOCKETED

<b>Docket Number:</b>	17-IEPR-11
<b>Project Title:</b>	Southern California Energy Reliability
<b>TN #:</b>	217874
<b>Document Title:</b>	Concerned Neighbor Comments IEPR Workshop
<b>Description:</b>	N/A
<b>Filer:</b>	System
<b>Organization:</b>	Concerned Neighbor
<b>Submitter Role:</b>	Public
<b>Submission Date:</b>	6/6/2017 8:30:19 AM
<b>Docketed Date:</b>	6/6/2017

*Comment Received From: Concerned Neighbor*

*Submitted On: 6/6/2017*

*Docket Number: 17-IEPR-11*

## **IEPR Workshop**

*Additional submitted attachment is included below.*

**Paul, Patricia@Energy**

---

**From:** D C <2borfold@gmail.com>  
**Sent:** Monday, June 05, 2017 9:45 PM  
**To:** Energy - Docket Optical System; Wong, Lana@Energy  
**Subject:** IEPR 2017-05-22 Workshop Public Comment

Major Earthquake Faults run under Aliso Canyon Storage Facility. Become familiar with Los Angeles Regional Water Quality Control Board findings.

Earthquake faults under Aliso Canyon Storage Facility. See here:

[https://geotracker.waterboards.ca.gov/esi/uploads/geo\\_report/4459785163/T10000008175.PDF#page=12&zoom=70,-74,1314](https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4459785163/T10000008175.PDF#page=12&zoom=70,-74,1314)

[https://geotracker.waterboards.ca.gov/esi/uploads/geo\\_report/4459785163/T10000008175.PDF#page=13&zoom=70,-74,1314](https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4459785163/T10000008175.PDF#page=13&zoom=70,-74,1314)

[https://geotracker.waterboards.ca.gov/esi/uploads/geo\\_report/4459785163/T10000008175.PDF#page=14&zoom=70,-74,1314](https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4459785163/T10000008175.PDF#page=14&zoom=70,-74,1314)

Concerned Neighbor, Chatsworth, CA 91311