

DOCKETED

Docket Number:	21-IEPR-05
Project Title:	Natural Gas Outlook and Assessments
TN #:	238519
Document Title:	California Energy Commission Comments - 2020 SDGE Dist DOT Report
Description:	N/A
Filer:	System
Organization:	California Energy Commission
Submitter Role:	Commission Staff
Submission Date:	6/25/2021 5:00:09 PM
Docketed Date:	6/25/2021

*Comment Received From: California Energy Commission
Submitted On: 6/25/2021
Docket Number: 21-IEPR-05*

2020 SDGE Dist DOT Report

Additional submitted attachment is included below.

NOTICE: This report is required by 49 CFR Part 191. Failure to report can result in a civil penalty not to exceed 100,000 for each violation for each day that such violation persists except that the maximum civil penalty shall not exceed \$1,000,000 as provided in 49 USC 60122.

OMB NO: 2137-0629
EXPIRATION DATE: 10/31/2021



U.S Department of Transportation
Pipeline and Hazardous Materials Safety Administration

Initial Date Submitted:

03/11/2021

Form Type:

INITIAL

Date Submitted:

**ANNUAL REPORT FOR
CALENDAR YEAR 2020
GAS DISTRIBUTION SYSTEM**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2137-0629. Public reporting for this collection of information is estimated to be approximately 16 hours per response, including the time for reviewing instructions, gathering the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, PHMSA, Office of Pipeline Safety (PHP-30) 1200 New Jersey Avenue, SE, Washington, D.C. 20590.

Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the PHMSA Pipeline Safety Community Web Page at <http://www.phmsa.dot.gov/pipeline/library/forms>.

PART A - OPERATOR INFORMATION

(DOT use only)

20210927-42347

1. Name of Operator	SAN DIEGO GAS & ELECTRIC CO
2. LOCATION OF OFFICE (WHERE ADDITIONAL INFORMATION MAY BE OBTAINED)	
2a. Street Address	555 West Fifth Street
2b. City and County	Los Angeles
2c. State	CA
2d. Zip Code	90013
3. OPERATOR'S 5 DIGIT IDENTIFICATION NUMBER	18112
4. HEADQUARTERS NAME & ADDRESS	
4a. Street Address	8326 CENTURY PARK COURT
4b. City and County	SAN DIEGO
4c. State	CA
4d. Zip Code	92123
5. STATE IN WHICH SYSTEM OPERATES	CA
6. THIS REPORT PERTAINS TO THE FOLLOWING COMMODITY GROUP (Select Commodity Group based on the predominant gas carried and complete the report for that Commodity Group. File a separate report for each Commodity Group included in this OPID.)	
Natural Gas	
7. THIS REPORT PERTAINS TO THE FOLLOWING TYPE OF OPERATOR (Select Type of Operator based on the structure of the company included in this OPID for which this report is being submitted.):	
Investor Owned	

PART B - SYSTEM DESCRIPTION

1.GENERAL

	STEEL				PLASTIC	CAST/ WROUGHT IRON	DUCTILE IRON	COPPER	OTHER	RECONDITION ED CAST IRON	SYSTEM TOTAL
	UNPROTECTED		CATHODICALLY PROTECTED								
	BARE	COATED	BARE	COATED							
MILES OF MAIN	0	0	0	3571	4665	0	0	0	0	0	8236
NO. OF SERVICES	0	0	0	279383	412294	0	0	0	0	0	691677

2.MILES OF MAINS IN SYSTEM AT END OF YEAR												
MATERIAL	UNKNOWN	2" OR LESS	OVER 2" THRU 4"	OVER 4" THRU 8"	OVER 8" THRU 12"	OVER 12"	SYSTEM TOTALS					
STEEL	0	1338	1737	339	110	47	3571					
DUCTILE IRON	0	0	0	0	0	0	0					
COPPER	0	0	0	0	0	0	0					
CAST/WROUGH T IRON	0	0	0	0	0	0	0					
PLASTIC PVC	0	0	0	0	0	0	0					
PLASTIC PE	0	318	4267	80	0	0	4665					
PLASTIC ABS	0	0	0	0	0	0	0					
PLASTIC OTHER	0	0	0	0	0	0	0					
OTHER	0	0	0	0	0	0	0					
RECONDITIOE D CAST IRON	0	0	0	0	0	0	0					
TOTAL	0	1656	6004	419	110	47	8236					
Describe Other Material:												
3.NUMBER OF SERVICES IN SYSTEM AT END OF YEAR												
											AVERAGE SERVICE LENGTH: 54	
MATERIAL	UNKNOWN	1" OR LESS	OVER 1" THRU 2"	OVER 2" THRU 4"	OVER 4" THRU 8"	OVER 8"	SYSTEM TOTALS					
STEEL	0	275626	3623	101	25	8	279383					
DUCTILE IRON	0	0	0	0	0	0	0					
COPPER	0	0	0	0	0	0	0					
CAST/WROUGH T IRON	0	0	0	0	0	0	0					
PLASTIC PVC	0	0	0	0	0	0	0					
PLASTIC PE	0	394167	17935	181	11	0	412294					
PLASTIC ABS	0	0	0	0	0	0	0					
PLASTIC OTHER	0	0	0	0	0	0	0					
OTHER	0	0	0	0	0	0	0					
RECONDITIOE D CAST IRON	0	0	0	0	0	0	0					
TOTAL	0	669793	21558	282	36	8	691677					
Describe Other Material:												
4.MILES OF MAIN AND NUMBER OF SERVICES BY DECADE OF INSTALLATION												
	UNKNOWN	PRE-1940	1940-1949	1950-1959	1960-1969	1970-1979	1980-1989	1990-1999	2000-2009	2010-2019	2020-2029	TOTAL

MILES OF MAIN	0	182	272	1148	1101	1414	1537	1038	1009	507	28	8236
NUMBER OF SERVICES	0	11964	17905	99166	89648	124905	125418	84143	80577	54883	3068	691677

PART C - TOTAL LEAKS AND HAZARDOUS LEAKS ELIMINATED/REPAIRED DURING THE YEAR

CAUSE OF LEAK	MAINS		SERVICES	
	TOTAL	HAZARDOUS	TOTAL	HAZARDOUS
CORROSION FAILURE	124	71	837	305
NATURAL FORCE DAMAGE	22	15	50	21
EXCAVATION DAMAGE	63	59	292	286
OTHER OUTSIDE FORCE DAMAGE	0	0	38	21
PIPE, WELD OR JOINT FAILURE	60	30	268	52
EQUIPMENT FAILURE	27	12	1164	86
INCORRECT OPERATIONS	9	6	79	10
OTHER CAUSE	54	28	37	18

NUMBER OF KNOWN SYSTEM LEAKS AT END OF YEAR SCHEDULED FOR REPAIR : 9

PART D - EXCAVATION DAMAGE

1. TOTAL NUMBER OF EXCAVATION DAMAGES BY APPARENT ROOT CAUSE: 418

a. One-Call Notification Practices Not Sufficient: 162

b. Locating Practices Not Sufficient: 9

c. Excavation Practices Not Sufficient: 70

d. Other: 177

2. NUMBER OF EXCAVATION TICKETS : 180875

PART E - EXCESS FLOW VALUE (EFV) AND SERVICE VALVE DATA

Total Number Of Services with EFV Installed During Year: 2845

Estimated Number Of Services with EFV In the System At End Of Year: 38109

* Total Number of Manual Service Line Shut-off Valves Installed During Year: 269

* Estimated Number of Services with Manual Service Line Shut-off Valves Installed in the System at End of Year: 900

**These questions were added to the report in 2017.*

PART F - LEAKS ON FEDERAL LAND

TOTAL NUMBER OF LEAKS ON FEDERAL LAND REPAIRED OR SCHEDULED TO REPAIR: 14

PART G-PERCENT OF UNACCOUNTED FOR GAS

UNACCOUNTED FOR GAS AS A PERCENT OF TOTAL CONSUMPTION FOR THE 12 MONTHS ENDING JUNE 30 OF THE REPORTING YEAR.

[(PURCHASED GAS + PRODUCED GAS) MINUS (CUSTOMER USE + COMPANY USE + APPROPRIATE ADJUSTMENTS)] DIVIDED BY (CUSTOMER USE + COMPANY USE + APPROPRIATE ADJUSTMENTS) TIMES 100 EQUALS PERCENT UNACCOUNTED FOR.

FOR YEAR ENDING 6/30: 3.66%

PART H - ADDITIONAL INFORMATION

PART I - PREPARER

James Dewberry

James Dewberry, Pipeline Integrity Team Lead
(Preparer's Name and Title)

(213)244-4514

(Area Code and Telephone Number)

JDewberry@socalgas.com
(Preparer's email address)

(Area Code and Facsimile Number)