

Docket Number:	09-AFC-07C
Project Title:	Palen Solar Power Project - Compliance
TN #:	200180
<b>Document Title:</b>	Applicant Response to CEC Data Request 57- Part 7.1
<b>Description:</b>	N/A
Filer:	Tiffani Winter
Organization:	Galati Blek, LLP
<b>Submitter Role:</b>	Applicant's Representative
ubmission Date:	8/13/2013 11:07:01 AM
<b>Docketed Date:</b>	8/13/2013

33-6913







State of California – The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
DDIMADY DECODD

PRIMARY	KECOKD	

Primary # <u>33-6914 Update</u> HRI #	
Trinomial	
NRHP Status Code 3B	
Reviewer	Date

Page 1 of 3

\*Resource Name or # (Assigned by recorder) Eagle Mountain Pumping Plant

P1. Other Identifier: Colorado River Aqueduct Pumping Plant

\*P2. Location: ☑ Not for Publication ☐ Unrestricted \*a. County Riverside

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

\*b. USGS 7.5' Quad Victory Pass Date 1987 T 4S R 15E; 1/4 of 1/4 of Sec 19; S.B.B.M.

Other Listings \_\_\_ Review Code

c. Address Eagle Mountain Road City Eagle Mountain Zip 92241

d. UTM: (give more than one for large and/or linear resources) Zone 11; a. 643800mE/ 3742200mN b. 643800mE/ 3741500mN

c. 643300mE/ 3741500mN d. 643300mE/ 3742200mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN: 807-150-001-2

\*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This resource was first surveyed in 1982 by the Riverside County Historical Community. The property was revisited on July 10, 2013 and reassessed as part of the current study because the previous evaluation occurred more than 5 years ago.

The resource was originally recorded as the Eagle Mountain Pumping Plant, built from 1936 to 1939 and associated with the Colorado River Aqueduct. The pumping plant complex consists of the main four-story Art Deco-style pumping building, three concrete delivery pipes connected to a surge tower, nine motors, nine pumps, a switch house, a concrete outlet, a reservoir, street lights, and three workers' houses. The structures on the property looked to be largely unchanged from last recording; however, a full observation of the property and its structures did not take place, as the gate to the road leading to the plant was closed, restricting access. The additional building were not accessible, but are also outside of the viewshed of indirect impacts for the current study.

\*P3b. Resource Attributes: (List attributes and codes) HP9. Public utilities building

\*P4. Resources Present: ⊠ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other (Isolates, etc.)

P5b. Description of Photo: (View, date, accession #) <u>Camera facing SW, 7/10/2013. DCSN 0475</u>

\*P6. Date Constructed/Age and Sources:

☑ Historic ☐ Prehistoric ☐ Both
ca. 1936/1982 DPR form

\*P7. Owner and Address:

Metropolitan Water District of Southern California
P.O. Box 54153

Los Angeles, CA 90053

\*P8. Recorded by: (Name, affiliation, address) M.K. Meiser, C. Recksieck

<u>AECOM</u>

1420 Kettner Blvd., Suite 500 San Diego, CA 92101

\*P9. Date Recorded: <u>7/10/2013</u>

\*P10. Survey Type: (Describe) Intensive

\*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Class II and III Cultural Resources Survey Report for the Palen Solar Electric Generating System Riverside County, California AECOM 2013

'Attachments:	NONE L	∠ Location M	ap ⊔ Ske	etch Map I		ation Sheet	∠ Building	, Structure,	and Obj	ect Record L	→ Archaeolog	jical Record
☐ District Reco	ord D Lin	ear Feature R	Record $\square$	Milling Sta	ation Recor	d $\square$ Rock A	rt Record I	Artifact F	Record [	7 Photograp	h Record	

☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record

□ Other (list)

State of California – The Resources Agency DEPARTMENT OF PARKS AND RECREATION

Primary # 33-6914 Update

HRI#

# **BUILDING, STRUCTURE, AND OBJECT RECORD**

Page 2 of 3

\*NRHP Status Code 3B

\*Resource Name or # (Assigned by recorder) Eagle Mountain Pumping Plant

B1. Historic Name: Eagle Mountain Pumping Plant

B2. Common Name: Eagle Mountain Pumping Plant

B3. Original Use: Aqueduct Pumping Station B4. Present Use: Aqueduct Pumping Station

\*B5. Architectural Style: Moderne/Art Deco

\*B6. Construction History: (Construction date, alteration, and date of alterations) Built in 1935, alterations include concrete block addition

\*B7. Moved? 

No □ Yes □ Unknown Date: Original Location:

\*B8. Related Features: None

B9. Architect: <u>Unknown</u> b. Builder: <u>Metropolitan Water District</u>

\*B10. Significance: Theme Industrial Development Area Eagle Mountain
Period of Significance 1936 Property Type Pumping Station Applicable Criteria A, C

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The Eagle Mountain Pumping Plant appears eligible for the NRHP and CRHR as a contributing element of the 242-mile-long Colorado River Aqueduct water conveyance system, with appears eligible for the NRHP and CRHR. Based on its direct association with the Colorado River Aqueduct, the Eagle Mountain Pumping Plant meets NRHP Criterion A and CRHR Criterion 1 and NRHP Criterion C and CRHR Criterion 3. The Eagle Mountain Pumping Plant is one of five pumping plants in the system, and one of two pumping plants within Riverside County (see also Hayfield Pumping Plant). Several segments of the Colorado River Aqueduct system have been previously recorded and evaluated, and the resource has been consistently recommended eligible under NRHP criteria A and C (Neves and Goodman 2000; Hamilton and Beedle 2005). The Colorado River Aqueduct is significant for its direct association with the economic development of Southern California and as a marvel of civil engineering, and is a National Historic Engineering Landmark. As part of the system, the Eagle Mountain Pumping Plant contributes to its significance in the economic development of Southern California, meeting NRHP Criterion A and CRHR Criterion 1. The plant was built between 1936 and 1939, and in addition to contributing to the engineering significance of the system, it was designed in the Art Deco style and is a good representative example of Art Deco in a utilitarian building, particularly rare in a remote area of the Chuckwalla Valley. It appears eligible individually under NRHP Criterion C and CRHR Criterion 3. The pumping plant retains its integrity in each of the seven aspects, and appears eligible for the NRHP and CRHR.

B11. Additional Resource Attributes: (List attributes and codes)

### \*B12. References:

Hamilton, M.C. and P. Beedle

 $2005\,$  DPR 523 forms for the Colorado River Acqueduct (P-33-11265). On file at EIC.

Neves, J. and J. Goodman


2000 DPR 523 forms for the Colorado River Acqueduct (P-33-11265). On file at EIC.

B13. Remarks:

\*B14. Evaluator: M.K. Meiser

\*Date of Evaluation: August 9, 2013

(This space reserved for official comments.)



State of California - The Resources Agency	
DEPARTMENT OF PARKS AND RECREATION	١

Primary #\_\_\_\_\_\_HRI #\_\_\_\_\_Trinomial

**LOCATION MAP** \* Resource Name or # (Assigned by recorder) P-33-6914 Page 3 of 3 \* Map Name: USGS Quad Victory Pass 1:24,000 \* Date of Map: 1983 \* Scale: 10337 Prospect WW 8227 10347 SITE LOCATION Landing Strip Prospect 1 MILE 2000 4000 5000 6000 7000 FEET

**CONTOUR INTERVAL 5 METERS** 

1 KILOMETER


QUADRANGLE LOCATION

			Ser. No	<u>33</u>	-2241	-2	_
HABS.		_ HAER	NR <u>4</u>	₫	SHL	Loc	
UTM:	Α	643800	NR 40	3	643800	1374/500	
	С	64330	7/374/500 C	) _4	6433 <i>0</i> 0	1374220	7

	HISTORIC RESOURCES INVENTORY	UTM: A <u>643800/3742200</u> B <u>643800/374/500</u> C <u>643300/374/50</u> 0 D <u>643300/3742200</u>
<b>(</b> ;	IDENTIFICATION 1. Common name: Eagle Mountain Pump	oing Plant 33-6914
	2. Historic name: Eagle Mountain Pump	oing Plant
	3. Street or rural address: sec. 19, T4S R1	.5E
	City Eagle Mountain	Zip 92241 County Riverside
	4. Parcel number: 807-150-001-2	
	5. Present Owner: USA 807 Dept. of I	nterior Address:
	City Washington, D.C. Zip	21401 Ownership is: Public X Private
	6. Present Use: Aqueduct Pumping Stat	ionOriginal use: Aqueduct Pumping Station
	DESCRIPTION 7a. Architectural style: Moderne/Art Deco	
	original condition: This is a multipl	the site or structure and describe any major alterations from its  e resource nomination including the
÷	following: the main pumping buildi tain to a surge tower, nine Westing	ng, three delivery pipes up the moun-
	workers' houses.  Central in this complex is the	four-story main pumping building which tory main control room attached to one

Constructed of reinforced concrete and steel, the side of the building. main pumping building has an additional three stories below ground level. There are elements of Moderne and Art Deco styling including at each end the department seal in cement, and small lamps, flat cement urns and curved cement curbs flanking the large arched entries. On each side of the building are located ten two-story high mullioned windows and curved raised flower beds on the earlier constructed section. Spanish tile hip roofs cap both the main building and the control room.

Three concrete delivery pipes extend from the rear of the building up the mountain side, converging in a cement structure before continuing parallel to a second structure at the top of the mountain, achieving a (cont. d. separate page)



	Estimated	. Factual	1936
	Architect		
-	• • • • • • • • • • • • • • • • • • •		

- Builder Metropolitan Water District
- Approx. property size (in feet) Frontage \_\_\_\_\_ \_ Depth\_ or approx. acreage 640 acres
- 2. Date(s) of enclosed photograph(s) March 27, 1982 18-79-31-31

13.	Condition: Excellent X Good Fair Deteriora	
14.	Alterations: None	33-6914
- <u>-</u>	Surroundings: (Check more than one if necessary) Open land ResidentialOther:	d X Scattered buildings Densely built-up Densely built-up Open space
16.	Threats to site: None known X Private development Public Works project Other:	Zoning Vandalism
17.	Is the structure: On its original site? X Moved?	Unknown?
18.	Related features: None	
	IFICANCE Briefly state historical and/or architectural importance (include	de dates, events, and persons associated with the site.)
of th Co in pl ar	five pumping stations on the Color e Hayfield plant are the only two sunty. The original building had roitially installed. As water demandeted, allowing its current (1982) n	oom for five pumps with only three lincreased, the building was comine pump capacity. Aside from its cain Pumping Plant is an engineering
	Main theme of the historic resource: (If more than one is checked, number in order of importance.)  Architecture X Arts & Leisure Economic/Industrial X Exploration/Settlement Government Military Social/Education	Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks):  ENGLE MOUNTAIN NORTH
21.	Sources (List books, documents, surveys, personal interviews and their dates).	KINEK HORING WORKER
	e Great Aqueduct by Metropolitan ter District of Southern California	A DIVE DIVE I
22.	Date form prepared July 28, 1982  By (name) Linda Warner  Organization Riv. Co. Historical Comm.  Address: 4600 Crestmore Rd.  City Rubidoux Zip 92519  Phone: (714) 787-2551	KA15ER ROHD
-		DESERT CEMTER LAWY 10, 3,3 MI. 2.5 MI.

State of California - The Resources Agency

	DEP	ARI	ME	NT OF	PAR	KS A	ND I	RECR	EATI
I	PR	IM	AR	YF	REC	OR	D		

Primary #\_ HRI# Trinomial NRHP Status Code Reviewer

Page 1 of 3

\*Resource Name or # (Assigned by recorder) P-BE-003

P1. Other Identifier: Pumping Station

\*P2. Location: ⊠ Not for Publication □ Unrestricted and (P2b and P2c or P2d. Attach a Location Map as necessary.)

\*a. County Riverside

\*b. USGS 7.5' Quad Desert Center Date 1986 T 6S R 15E; SE¼ of NE¼ of Sec 26; S.B.B.M.

Other Listings Review Code

c. Address 43025 Aztec Ave City Anza Zip 92539

d. UTM: (give more than one for large and/or linear resources) Zone  $\underline{11}$ ;  $\underline{650136}$ mE/  $\underline{3730985}$ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 808-112-006

\*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This resource is a pumping station located at 43025 Aztec Ave (Parcel 808-112-006) south of Interstate 10 near Desert Center. The resource is a tall steel utilitarian facility with a series of pipelines. The second level is accessed by metal stairs. Stack vents are on the roof and fenestration consists of metal-framed multi-light windows. It is enclosed by a cyclone fence topped with barbwire.

\*P3b. Resource Attributes: (List attributes and codes) HP39. Other

\*P4. Resources Present: ⊠ Building □ Structure □ Object □ Site □ District □ Element of District □ Other (Isolates, etc.)

P5b. Description of Photo: (View, date, accession #) Camera facing SE, 7/11/2013. DSCN 0180.

\*P6. Date Constructed/Age and Sources: ca. 1960/USGS topographic map

\*P7. Owner and Address: Southern California Gas Company 101 Ash Street San Diego, CA 92101

\*P8. Recorded by: (Name, affiliation, address) M.K. Meiser, C. Recksieck AECOM 1420 Kettner Blvd., Suite 500 San Diego, CA 92101

\*P9. Date Recorded: 7/11/2013

\*P10. Survey Type: (Describe) Intensive

\*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Class II and III Cultural Resources Survey Report for the Palen Solar Electric Generating System Riverside County, California AECOM 2013

'Attachments:	NONE		Лар Ц≕	Sketch Map	Ш	Continuation S	Sheet ഥ	Building,	Structure,	and Ob	oject Record I		ogical Reco	ord
☐ District Reco	rd □ I	inear Feature	Record	☐ Milling S	tatio	on Record 🗖 I	Rock Art	Record [	Artifact F	Record	☐ Photogram	h Record		

☐ Other (list)

DPR 523A (1/95)

\*Required Information

State of California – The Resources Agency DEPARTMENT OF PARKS AND RECREATION

Primary # HRI #

# **BUILDING, STRUCTURE, AND OBJECT RECORD**

Page 2 of 3

\*NRHP Status Code

\*Resource Name or # (Assigned by recorder) 808-112-006

B1. Historic Name: N/A
B2. Common Name: N/A

B3. Original Use: Pumping Station B4. Present Use: Pumping Station

\*B5. Architectural Style: Utilitarian

\*B6. Construction History: (Construction date, alteration, and date of alterations) ca. 1960

\*B7. Moved? ⊠ No ☐ Yes ☐ Unknown Date: Original Location:

\*B8. Related Features: None

B9. Architect: <u>Unknown</u> b. Builder: <u>Unknown</u>

\*B10. Significance: Theme Community Development

Period of Significance 1960 Property Type Pump Station

Area Desert Center

Applicable Criteria N/A

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The resource appears on the 1963 USGS Chuckwalla Mountains Topographic Map and has components that are 50 or more years old. Based on historic map information and visual observation the resource likely dates to 1960.

The pumping station does not appear to meet the criteria for the CRHR. The facility was built during a period when Desert Center was undergoing improvements including the arrival of commercial electricity. In the late 1940s, Kaiser established the Eagle Mountain Mining Company 11 miles from Desert Center. The mine included a company town supporting dozens of employees and their families. The successful operation of the mine from the late 1940s to early 1980s (when the mine closed) benefitted the community of Desert Center. During this period, Desert Center saw the establishment of the Desert Center Unified School District, the growth of the Desert Center Community Church, and the arrival of commercial electricity (Desert Center Chamber of Commerce 2010). The pumping plant was built during this period of community improvements and although the facility served a useful purpose as a pumping station for the community, it does not appear to have made a significant contribution to the history of the region, overall and therefore does not appear to qualify for listing under Criterion 1 of the CRHR. The structure is also not known to be associated with significant persons in the area, and therefore do not appear to qualify under Criterion 2 of the CRHR. As a utilitarian structure, the pumping station does not appear to qualify as significant or unique in the distinctive characteristics of a type, period, or method of construction. Therefore, it does not appear to meet Criterion 3 of the CRHR. Under consideration of all criteria, the pumping plant does not appear to meet the criteria for listing in the CRHR.

B11. Additional Resource Attributes: (List attributes and codes)

\*B12. References: 1963 USGS Chuckwalla Mountains Topographic Map, Desert Center Chamber of Commerce 2010

B13. Remarks:


\*B14. Evaluator:

Madeline Bowen, AECOM

\*Date of Evaluation:

August 7, 2013


(This space reserved for official comments.)



LOCATION MAP
<b>DEPARTMENT OF PARKS AND RECREATION</b>
State of California - The Resources Agency

Primary #\_\_\_\_\_\_HRI #\_\_\_\_\_\_Trinomial\_\_\_\_\_\_

Page 3 of 3 \* Resource Name or # (Assigned by recorder) P-BE-003



State of California - The Resources Agency

DEPA	ARTMEN	IT OF P	ARKS A	ND RE	CREATI
PRI	MAR	Y RE	COR	D	

Primary #\_ HRI# Trinomial NRHP Status Code Reviewer

Page 1 of 3

\*Resource Name or # (Assigned by recorder) 24475 Rice Rd.

P1. Other Identifier: P-BE-004

\*P2. Location: 

Not for Publication □ Unrestricted \*a. County Riverside

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

\*b. USGS 7.5' Quad <u>East of Victory Pass</u> Date <u>1986</u> T <u>5S</u> R <u>16E; SE¼ of NW¼ of Sec 5; S.B.B.M.</u>

Other Listings

Review Code

c. Address 24475 Rice Road City Desert Center Zip 92239

d. UTM: (give more than one for large and/or linear resources) Zone 11; 653944mE/ 3737656mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 811-121-003

\*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This resource is a residential cluster of vernacular buildings located at 24475 Rice Rd (Parcel 811-121-003) that appears to date from circa 1960 (based on topographic maps and visual observation). There are two main residential buildings and several secondary buildings and sheds on the parcel. The two residential buildings are one-story Ranch-style vernacular residences with low-pitched roofs, synthetic or mixed siding, mixed wood, aluminum and synthetic windows, and full-length porches. Another building appears to be a converted mobile home. Another primary building is a one-story residence with a rectangular plan, clapboard siding, a low-pitched roof, wood multi-light sash windows, and a five-panel wood door. Two other clapboard sided buildings are located on the parcel.

\*P3b. Resource Attributes: (List attributes and codes) HP3. Multiple family property

\*P4. Resources Present: ⊠ Building □ Structure □ Object □ Site □ District □ Element of District □ Other (Isolates, etc.)

P5b. Description of Photo: (View, date, accession #) Camera facing NW, 7/11/2013. DSCN 0068

\*P6. Date Constructed/Age and Sources: ca. 1960/Source; 1963 USGS topographic map, visual observation

\*P7. Owner and Address: Charlene R. Carney PO Box 411 Desert Center, CA 92239

\*P8. Recorded by: (Name, affiliation, address) M.K. Meiser, C. Recksieck AECOM 1420 Kettner Blvd., Suite 500 San Diego, CA 92101

\*P9. Date Recorded: 7/11/2013

\*P10. Survey Type: (Describe) Intensive

\*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Class II and III Cultural Resources Survey Report for the Palen Solar Electric Generating System Riverside County, California AECOM 2013

*Attachments:	NONE	Location №	Иар <b>⊔</b> Sketch	Map ☐ Cor	ntinuation Sheet	I≱ Building,	Structure, an	d Object Record	□ Archaeological	Record
☐ District Reco	rd Di	inear Feature	Record   Mill	ing Station R	ecord   Rock	Art Record [	Artifact Rec	ord $\square$ Photograp	nh Record	

☐ Other (list)

State of California – The Resources Agency
<b>DEPARTMENT OF PARKS AND RECREATION</b>

Primary #	
HRI#	

# **BUILDING, STRUCTURE, AND OBJECT RECORD**

Page 2 of 3

\*NRHP Status Code

\*Resource Name or # (Assigned by recorder) 811-121-003

B1. Historic Name: N/A
B2. Common Name: N/A

B3. Original Use: Residence B4. Present Use: Residence

\*B5. Architectural Style: Ranch-style vernacular

\*B6. Construction History: (Construction date, alteration, and date of alterations) ca. 1950s-1960s

\*B7. Moved? ⊠ No ☐ Yes ☐ Unknown Date: Original Location:

\*B8. Related Features: Sheds, converted mobile home

B9. Architect: <u>Unknown</u> b. Builder: <u>Unknown</u>

\*B10. Significance: Theme Residential Development Area Desert Center

Period of Significance 1950-1960 Property Type Residence Applicable Criteria N/A

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The property does not appear to meet the criteria for the CRHR. The resource appears on the 1963 USGS Chuckwalla Mountains Topographic Map and has components that are 50 or more years old. Little information is known about this property, however, it was developed during a period when individuals were taking advantage of the Desert Land Act, passed in 1877. Through the act, Congress encouraged and promoted the economic development of arid land such as that found in the Chuckwalla Valley. Many of these claims were made in the vicinity of Rice Road in Desert Center. Settlers often lived in converted trailers on their newly claimed land or built their own homes from rock, wood, or concrete (Anderson 1998). As it became evident that wells could be successfully drilled for irrigation, more families were drawn to the Desert Center area. The success of the nearby Eagle Mountain Mine also contributed to growth in the desert community.

Individually, the property does not appear to have made a significant contribution to the history of Desert Center, and, therefore, does not appear to qualify for listing under Criterion 1 of the CRHR. Under Criterion 2 of the CRHR, the property does not appear to have any known associations with significant persons. Under Criterion 3 of the CRHR, the buildings do not possess architectural significance and are humble structures that do not embody the distinctive characteristics of a type, period, or method of construction. Lastly, the buildings have deteriorated over time and therefore do not retain sufficient integrity to meet CRHR eligibility. For these reasons, the property does not appear to meet the criteria for listing in the CRHR.

B11. Additional Resource Attributes: (List attributes and codes)

### \*B12. References:

Anderson, Robert E. "My Part in the History of Chuckwalla Valley I-III", c 1998

B13. Remarks:


#### \*B14. Evaluator:

Madeline Bowen, AECOM

### \*Date of Evaluation:

August 7, 2013

(This space reserved for official comments.)



LOCATION MAP
<b>DEPARTMENT OF PARKS AND RECREATION</b>
State of California - The Resources Agency

Primary #\_\_\_\_\_\_HRI #\_\_\_\_\_\_Trinomial

Page 3 of 3 \* Resource Name or # (Assigned by recorder) P-BE-004

\* Map Name: USGS Quad East of Victory Pass 1:24,000 \* Date of Map:1983 \* Scale: 31 Well 548 Well 5451 SITE LOCATION RISE 1-111 1-112 BM 585 1 MILE 2000 3000 4000 5000 6000 7000 FEET 1000 1000 1 KILOMETER **CONTOUR INTERVAL 5 METERS** QUADRANGLE LOCATION State of California – The Resources Agency **DEPARTMENT OF PARKS AND RECREATION** 

_					ь.		<u> </u>	<b>D</b>
Ч	ĸ	IIVI	A٢	(Y	ΚI	EC(	UK	עו

Primary #\_ HRI# Trinomial NRHP Status Code \_\_\_\_\_ Reviewer

Page 1 of 3

\*Resource Name or # (Assigned by recorder) 22100 Rice Rd.

P1. Other Identifier: P-BE-005

\*P2. Location: ⊠ Not for Publication □ Unrestricted \*a. County Riverside and (P2b and P2c or P2d. Attach a Location Map as necessary.)

\*b. USGS 7.5' Quad <u>East of Victory Pass</u> Date <u>1986</u> T <u>5S</u> R <u>16E; SE¼ of NW¼ of Sec 5;</u> S.B.B.M.

c. Address 22100 Rice Road City Desert Center Zip 92239

d. UTM: (give more than one for large and/or linear resources) Zone 11; 654576mE/ 3737958mN

Other Listings

Review Code

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 811-122-004

☐ Other (list)

\*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This resource is a residential and agricultural property located at 22100 Rice Road (Parcel 811-122-004). It includes a onestory, Ranch-style residence with low-pitched side-gabled roof, stucco siding, replacement vinyl windows, and a recessed porch with square posts. The property also contains a shed outhouse.

\*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property, HP33. Farm/Ranch

\*P4. Resources Present: ⊠ Building □ Structure □ Object □ Site □ District □ Element of District □ Other (Isolates, etc.)



P5b. Description of Photo: (View, date, accession #) Camera facing S, 7/11/2013. DSCN\_0071.

\*P6. Date Constructed/Age and Sources: 

ca. 1960/Source: USGS Topographic, visual observation

\*P7. Owner and Address:

Ida Mae Edwards 1866 West 94th Place Los Angeles, CA 90047

\*P8. Recorded by: (Name, affiliation, address) M.K. Meiser, C. Recksieck AECOM 1420 Kettner Blvd., Suite 500 San Diego, CA 92101

\*P9. Date Recorded: 7/11/2013

\*P10. Survey Type: (Describe) Intensive

\*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Class II and III Cultural Resources Survey Report for the Palen Solar Electric Generating System Riverside County, California AECOM 2013

'Attachments:	NONE	Location Map L	J Sketch Map ∟	Continuation Sh	eet 🖾 Building	, Structure, and O	bject Record L	Archaeological Record	
District Reco	rd 🗆 Li	near Feature Reco	rd $\square$ Milling Sta	tion Record   Re	ck Art Record	Artifact Record	☐ Photograph	Record	

State of California – The Resources Agency	
DEPARTMENT OF PARKS AND RECREATION	Ν

Primary #	
HRI#	

# **BUILDING, STRUCTURE, AND OBJECT RECORD**

Page 2 of 3

\*NRHP Status Code 6Z

\*Resource Name or # (Assigned by recorder) 22100 Rice Rd.

B1. Historic Name: N/A
B2. Common Name: N/A

B3. Original Use: Residence/Farm B4. Present Use: Residence/Farm

\*B5. Architectural Style: Ranch-style

\*B6. Construction History: (Construction date, alteration, and date of alterations) Over 50 years old construction date unknown

\*B7. Moved? ⊠ No ☐ Yes ☐ Unknown Date: Original Location:

\*B8. Related Features: None

B9. Architect: <u>Unknown</u> b. Builder: <u>Unknown</u>

\*B10. Significance: Theme Residential/Agricultural Development Area Desert Center

Period of Significance ca 1960 Property Type Residence/Farm Applicable Criteria N/A

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

The property does not appear to meet the criteria for the CRHR. The resource appears on the 1963 USGS Chuckwalla Mountains Topographic Map and has components that are 50 or more years old. Based on historic map information and visual observation, the parcel was likely developed circa 1960. Little information is known about this property, however, it was developed during a period when individuals were taking advantage of the Desert Land Act passed in 1877. Through the act, Congress encouraged and promoted the economic development of arid land such as that found in the Chuckwalla Valley. Many of these claims were made in the vicinity of Rice Road in Desert Center. Settlers often lived in converted trailers on their newly claimed land or built their own homes from rock, wood, or concrete (Anderson 1998). As it became evident that wells could be successfully drilled for irrigation, more families were drawn to the Desert Center area. The success of the nearby Eagle Mountain Mine also contributed to growth in the desert community.

Although this property has played a general role in the growth of Desert Center, it is not known to be directly associated with events that have made a significant contribution to the history of the area and therefore does not appear to meet Criterion 1 of the CRHR. The property is not known to be associated with significant persons in area history; therefore, the property does not appear to meet Criterion 2 of the CRHR. The residence does not display distinctive characteristics of a type, period, or method of construction and thus does not appear to meet Criterion 3. The residence was also changed through the replacement of windows and siding. The physical condition of the property has also deteriorated over time. In summary, the property does not appear to meet the criteria for listing in the CRHR.

B11. Additional Resource Attributes: (List attributes and codes)

\*B12. References: "My Part in the History of Chuckwalla Valley I-III", c 1998

B13. Remarks:

\*B14. Evaluator: Madeline Bowen, AECOM

\*Date of Evaluation:

August 7, 2013

(This space reserved for official comments.)

