DOCKETED	
Docket Number:	21-IEPR-03
Project Title:	Electricity and Natural Gas Demand Forecast
TN #:	238039
Document Title:	DOT PHMSA 2020 GD Submitted Report
Description:	As part of the supporting data, the IEPR Gas Forms submittal requires PG&E to provide the most recent U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration (PHMSA) Gas Distribution F7100.1-1, Gas Transmission and Gathering F7100.2-1, and Underground Natural Gas Storage F7100.4-1 submitted by the gas utility.
Filer:	Elizabeth Lopez
Organization:	PG&E
Submitter Role:	Public Agency
Submission Date:	5/28/2021 11:36:26 AM
Docketed Date:	5/28/2021

NOTICE: This report is required by 49 CFR Part 191. Failure to report can result in a civil pexceed 100,000 for each violation for each day that such violation persists except that the penalty shall not exceed \$1,000,000 as provided in 49 USC 60122.	OMB NO: 2137-0629 EXPIRATION DATE: 10/31/2021	
	Initial Date Submitted:	02/25/2021
U.S Department of Transportation Pipeline and Hazardous Materials Safety Administration	Form Type:	INITIAL
	Date Submitted:	

ANNUAL REPORT FOR CALENDAR YEAR 2020 GAS DISTRIBUTION SYSTEM

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2137-0629. Public reporting for this collection of information is estimated to be approximately 16 hours per response, including the time for reviewing instructions, gathering the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, PHMSA, Office of Pipeline Safety (PHP-30) 1200 New Jersey Avenue, SE, Washington, D.C. 20590.

Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the PHMSA Pipeline Safety Community Web Page at http://www.phmsa.dot.gov/pipeline/library/forms.

PART A - OPERATOR INFORMATION	(DOT	use only)		20210496-41866		
1. Name of Operator	PACIFIC GA	S & ELECTF	RIC CO			
2. LOCATION OF OFFICE (WHERE ADDITIONAL INFORMATION MAY BE OBTAINED)						
2a. Street Address		6111 BOLLII	NGER CANY	ON RD #4430H		
2b. City and County		SAN RAMO	N			
2c. State		CA				
2d. Zip Code		94583				
3. OPERATOR'S 5 DIGIT IDENTIFICATION NUMBER		15007				
4. HEADQUARTERS NAME & ADDRESS						
4a. Street Address		PG&E - GAS OPERATIONS, REGULATORY COMPLIANCE, 6111 BOLLINGER CANYON RD.,				
4b. City and County		SAN RAMON				
4c. State		CA				
4d. Zip Code		94583				
5. STATE IN WHICH SYSTEM OPERATES		CA				
6. THIS REPORT PERTAINS TO THE FOLLOWING COMMODITY GRO complete the report for that Commodity Group. File a separate report for each commodity Group.						
Natural Gas						
7. THIS REPORT PERTAINS TO THE FOLLOWING TYPE OF OPERATioncluded in this OPID for which this report is being submitted.):	OR (Sele	ct Type of Op	erator based	on the structure of the company		
Investor Owned						

PART B - SYSTEM DESCRIPTION

1.GENERAL

STEEL											
	UNPRO	OTECTED CATHODICALLY PROTECTED		PLASTIC			COPPER	OTHER	RECONDITION ED	SYSTEM TOTAL	
	BARE	COATED	BARE	COATED		IRON	IRON			CAST IRON	
MILES OF MAIN	2.81	263.16	25.78	19434.83	23727.62	54.93	0	0	0	0	43509.13
NO. OF SERVICES	4	8446	301	1141950	2455501	30	0	138	0	0	3606370

MATERIAL STEEL DUCTILE IRON COPPER	UNKNOWN 15.68	2" OR LESS		OVER 2"	OVER 4	"		VER 8"			63/20		
DUCTILE IRON	15.68			THRU 4"	THRU 8			HRU 12"	OVE	₹ 12"	SYSTEM	TOTALS	
		12682.09		5069.61	1692.20	0		154.15	112	2.85	1972	6.58	
COPPER	0	0		0	0			0	()	(0	
	0	0		0	0			0	()	()	
CAST/WROUGH T IRON	.45	31.09		18.59	4.73			.07	()	54.	93	
PLASTIC PVC	0	0		0	0			0	()	()	
PLASTIC PE	3.59	18363.98		4399.86	960.14			.05	()	2372	7.62	
PLASTIC ABS	0	0		0	0			0	()	()	
PLASTIC OTHER	0	0		0	0			0	()	()	
OTHER	0	0		0	0			0	()	()	
RECONDITIONE D CAST IRON	0	0		0	0			0	()	()	
TOTAL	19.72	31077.16		9488.06	2657.0	7		154.27	112	2.85	4350	9.13	
Describe Other	Material:												
		<u> </u>											
3.NUMBER OF SE	RVICES IN SYSTE	M AT END OF Y	EAR			A۱	/ERAG	E SERVICE	LENGTH: 49.	7			
MATERIAL	UNKNOWN	1" OR LESS		OVER 1" THRU 2"	OVER 2 THRU 4			VER 4" 'HRU 8"	OVE	R 8"	SYSTEM	TOTALS	
STEEL	18587	1080777		50331	880			77	4	9	1150)701	
DUCTILE IRON	0	0		0	0			0	()	()	
COPPER	1	137	137 0		0			0	()	138		
CAST/WROUGH T IRON	0	26		4	0			0	()	3	0	
PLASTIC PVC	0	0		0	0			0	0		0		
PLASTIC PE	10068	2400751		43445	1171			57	Ş)	2455	5501	
PLASTIC ABS	0	0		0	0			0	(0)	
PLASTIC OTHER	0	0		0	0		0 0)	0			
OTHER	0	0 0 0 0)	()							
RECONDITIONE D CAST IRON	0	0	0 0		0	0		0 0)	0		
TOTAL	28656	3481691 93780		2051	2051 134		58		3606	6370			
Describe Other	Material:				1						<u>l</u>		
4.MILES OF MAIN	AND NUMBER O	F SERVICES BY	DECADE	OF INSTALL	ATION								
	PRE-												

MILES OF MAIN	256.92	1394. 57	3025.27	6140.27	6579.46	6226.71	5942.93	5584.37	5286.42	2818.47	253.74	43509.13
NUMBER OF SERVICES	445306	25397	98571	368307	344023	465328	480364	514365	488461	351125	25123	3606370

PART C - TOTAL LEAKS AND HAZARDOUS LEAKS ELIMINATED/REPAIRED DURING THE YEAR

	MAINS	SERVICES		
TOTAL	HAZARDOUS	TOTAL	HAZARDOUS	
954	377	3141	2549	
72	44	442	278	
213	198	1383	1363	
8	8	267	257	
92	59	1503	1065	
294	191	4161	1027	
459	206	2842	1893	
67	36	8196	1266	
	954 72 213 8 92 294 459	TOTAL HAZARDOUS 954 377 72 44 213 198 8 8 92 59 294 191 459 206	TOTAL HAZARDOUS TOTAL 954 377 3141 72 44 442 213 198 1383 8 8 267 92 59 1503 294 191 4161 459 206 2842	

NUMBER OF KNOWN SYSTEM LEAKS AT END OF YEAR SCHEDULED FOR REPAIR : (

PART D - EXCAVATION DAMAGE	PART E - EXCESS FLOW VALUE (EFV) AND SERVICE VALVE DATA
1. TOTAL NUMBER OF EXCAVATION DAMAGES BY APPARENT ROOT CAUSE: <u>1698</u>	Total Number Of Services with EFV Installed During Year: 17167
a. One-Call Notification Practices Not Sufficient: 731	Estimated Number Of Services with EFV In the System At End Of Year: 378751
b. Locating Practices Not Sufficient: 171 c. Excavation Practices Not Sufficient: 785	* Total Number of Manual Service Line Shut-off Valves Installed During Year: 1901
d. Other: 11	* Estimated Number of Services with Manual Service Line Shut-off Valves Installed in the System at End of Year: 94881
	*These questions were added to the report in 2017.
2. NUMBER OF EXCAVATION TICKETS : 1534928	
PART F - LEAKS ON FEDERAL LAND	PART G-PERCENT OF UNACCOUNTED FOR GAS
TOTAL NUMBER OF LEAKS ON FEDERAL LAND REPAIRED OR SCHEDULED TO REPAIR: 21	UNACCOUNTED FOR GAS AS A PERCENT OF TOTAL CONSUMPTION FOR THE 12 MONTHS ENDING JUNE 30 OF THE REPORTING YEAR. [(PURCHASED GAS + PRODUCED GAS) MINUS (CUSTOMER USE + COMPANY USE + APPROPRIATE ADJUSTMENTS)] DIVIDED BY (CUSTOMER USE + COMPANY USE + APPROPRIATE ADJUSTMENTS) TIMES 100 EQUALS PERCENT UNACCOUNTED FOR. FOR YEAR ENDING 6/30:0.71%_
PART H - ADDITIONAL INFORMATION	

PART I - PREPARER	
Susie Richmond,Mgr. Gas Ops Compliance (Preparer's Name and Title)	(925) 786-0267 (Area Code and Telephone Number)
Susie.Richmond@pge.com (Preparer's email address)	(Area Code and Facsimile Number)